

MOULDED PANEL

FD30 35mm

– INTERNAL FIRE DOOR

SPECIFICATIONS

Fire Rating

FD30 35mm 30 minute to BS476:Part 22: 1987 (CERTIFIRE CF572).

Construction

Moulded wood fibre face with softwood stiles and rails. FD30 Magnesium oxide board core.

Door Codes

Arlington 6 panel smooth (enhanced bead detail)	ARL35F
Atherton 4 panel smooth	ATH35F
Bostonian 6 panel woodgrain	BTN35F
Cambridge 2 panel smooth	CAMB35F
Camden 2 panel woodgrain	CMN35F
Oakfield 4 panel woodgrain	OFD35F
Newark woodgrain	NEWA35F
Linea smooth	LINE35F
Cube smooth	CUBE35F
Newbridge smooth	NEWB35F

Moisture Content

10% (+/-2%) in accordance with BS:EN942.

Facings

3.0mm die-formed moulded wood fibre skin.

Components

Stiles:	Softwood min 28mm (nominal width)
Rails (outer):	Softwood min 28mm (nominal width)
Rails (inner):	Softwood min 28mm (nominal width)
Core:	Magnesium oxide board
Lockblock:	N/A
Lipping:	N/A

Lock Area

Locks and handles may be fitted centrally in height either side of the door.

Finish

Supplied white primed for paint finish on site.

Maximum Trim

6mm from the bottom of the door and 4mm from each vertical edge.
The top of the door is not allowed to be trimmed due to the BWF-Certifire fire certification label and manufacturing identifications.

Installation Note

The doors have been tested to BS476 pt 22:1987 and are approved by BWF-Certifire of being capable of achieving 30 minute fire resistance when fitted in accordance with the installation instruction delivered with every door.

All doors must be fitted with intumescent strips to the top and sides of the door leaf or frame.

1mm intumescent sheets are supplied with the door for use around lock/latch area.

Cutting of apertures or glazing on site is not permitted and invalidates the fire certification.

Third party BWF-Certifire licensed processors are able to complete this ancillary work when required.

Maintenance

We recommend wiping down all surfaces with a clean damp cloth at least 4 times per year. We do not recommend using cleaning solutions or abrasive materials as this will damage the door.

Re-decorate the door as necessary always following the paint manufacturer's instructions.

